

A8 mini Firmware Update Log

Date: 2025-06-09

Camera Firmware Version: 0.3.2

Gimbal Firmware Version: 0.4.3

Update content:

Bug Fixed:

1. After controlling the gimbal by clicking “return to center” in the UniGCS app, the flight controller cannot control the gimbal via the SIYI protocol.
 2. After taking photos, UniGCS did not display the “take picture success” prompt.
 3. Some known issues.
-